

| Allotment | Area | Boundary | Plots | Vacant Plots | No. on waiting list | Meters | Estimated Cost (£70/m) |
|--|-------|--|-------|--------------|---------------------|--------------|------------------------|
| Alexandra Road (between 51 & 53 Alexandria Road) | SOUTH | DERELICT - Other sites in area have land that could be brought back in to use. | | | | Not Required | |
| Alexander Road | SOUTH | Boundary rope and posts (Average) / Main path from main gates (Average) / Metal mesh fencing along from side of the allotment and along the back (As new) / Mix wooden fencing at left side of allotment from private dwellings / Slabbed pathway where some are broken (Average) | 14 | 0 | 1 | Not Required | |
| Beechtree Road | EAST | Perimeter fencing metal (Good) Community building located on left after main gates may have asbestos roof. In between plots they maybe using asbestos panels as fencing. | 15 | 2 | 0 | Not required | |
| Blakenall Lane | NORTH | Chain Link fence (Average) with hedggrow / Footpath leading to the allotment from leamore park (Average) | 18 | 0 | 1 | Not Required | |
| Broad Lane | NORTH | The perimeter fencing is in good condition, metal pallasade. No issues regarding security or fencing | 27 | 0 | 2 | Not Required | |
| Clayhanger Lane | EAST | The site has no issues at all regarding boundaries, they are all secure with pallasade fencing. | 16 | 0 | 10 | Not Required | |
| Delves Green Road 1 | SOUTH | Really good allotment, all boundaries are metal or with proper hedgrow to support the boundaries. This allotment is financially secure | 49 | 0 | 10 | Not Required | |
| Goscote Lane | NORTH | Front gate gets flooded in bad weather. Perimeter is fine, all metal fencing | 101 | 1 | 1 | Not Required | |
| Greenfields Road | EAST | Fencing and security was in good condition (Pallasade fencing and good locks). Drive needs to be done - there was quote that was done last year | 96 | 0 | 15 | Not needed | |
| Huntington Road (New Invention) | WEST | Overall site in good condition, the poor boundry that was stated in the PSS report as now been upgraded and is now at a good level, toilet facilities are poor. Site as one access point from a neighbour house who has a plot on site. | 17 | 0 | 3 | Not Required | |
| Sneyd Lane (Dudley Fields) | NORTH | Overall site is in good condition. | 20 | 0 | 4 | Not Required | |
| Sutton Road | SOUTH | The main path leading up to the allotment gates, and the pathway in the allotment is all pebbly and can cause large puddles when raining. The allotment is in a good condition. | 83 | 0 | 25 | Not Required | |
| Wimperis Way (Pheasey) | EAST | The perimeter is in good condition, metal pallasade all around the allotment / gravel pathways in the allotment degraded. Gate in good condition | 58 | 0 | 22 | Not needed | |
| Adenbrook Street | WEST | Wooden fencing all around, right side of the allotment needs to be rectified as posts are tilting. | 28 | 0 | 14 | 108 | £7,560 |
| Alfred Street | WEST | New fencing required along the right and back of the site. Front and left, both in good condition - recently replaced. | 21 | 0 | 0 | 101 | £7,070 |
| Bentley Mill Way Allotments | WEST | This allotment is in very good condition. Main gates are pallasade, the left side of the allotment is high mesh fencing with barbed wire which needs replacing. | 14 | 0 | 14 | 129 | £9,030 |
| Borneo Street | SOUTH | Allotment is well maintained. The boundary is a mixture of wood, trees, hedgrow, mesh and pallasade fencing. Front gate needs to be replaced due to only being mesh with barbed wire on top, along with the fencing surrounding the front gate. Rightside of from the beginning of the gate is pallasade for approx 2 or 3 meters, then mesh fencing, and the same at the bottom of the fencing, in the middle is mesh fencing which overlooks the main road, - this requires pallasade fencing. The left side of the allotment is half mesh from the front gate, and then turns to pallasade. | 40 | 0 | 30 | 134 | £9,380 |
| Broadway (between 191 & 193 Broadway) | SOUTH | There are a lot of broken areas of metal wire fence especially around the disused area of the allotments where intruders have gained access in the past. | 73 | 16 | 0 | 460 | £32,200 |
| Cartbridge Lane | EAST | Will require fencing on the right hand side of the car park, everywhere else is pallasade fencing. | 28 | 0 | 0 | 86 | £6,020 |
| Clarks Lane | WEST | Leased by Council from Rubery Own - Boundary far right corner (needs a lot of work, full of brambles and bushes) / Left side wooden fence (Needs work) / Overgrown area at right hand corner of site / Pallasade metal fencing rear of the allotment that includes barbed wire | 21 | 0 | 3 | 100 | £7,000 |
| Delves Green Road 2 | SOUTH | One shared border to adjacent houses has gaps in the fencing where residential gardens back onto the allotment. There are gaps in metal fencing at the back of the allotment. | 40 | 0 | 11 | 247 | £17,290 |
| Dovedale Avenue | WEST | Gate secure, the other gate entering could be replaced, but not essential due to the main gate on the road. Leftside of the allotment is private fencing which is wooden. Right and back of allotment is green high mesh criss cross new fencing. | 15 | 0 | 25 | 29 | £2,030 |
| Forest Avenue | NORTH | overall site is in good condition, the boundary fence is a 6 feet chainmail fence with concrete posts which is within a good standard apart from to the rear left of the site where the fence has been damaged, this is also where trespassers enter the site and is causing security issues and ASB | 20 | 1 | 0 | 83 | £5,810 |
| Grenfell Road | NORTH | The perimeter is good, but at main gate may need pallasade fencing as currently mesh with no headgrow at the gate which could be a problematic. The brook on the site needs to be cleared - the pathway is broken and gets flooded constantly, especially near the brook and the car park in the allotment site which can not be used, very uneven pathway. 101 plots however only 80 useable | 80 | 0 | 11 | 1 | £70 |
| Huckers Road | SOUTH | Left side fencing needs replacing, in disrepair - it has wooden broken fencing and criss cross mesh which is waist high. The back of the allotments fencing is a mixture of trees, hedegrow, bushes and chain link fencing, which also needs replacing. Right side fencing is chain link, but this is in good condition. | 50 | 0 | 1 | 208 | £14,560 |
| Ince Road | WEST | Allotment requires fencing on the right hand side of the allotment where there is another gate which needs to be fenced off. | 13 | 0 | 1 | 34 | £2,380 |
| Lane Avenue / Parkbrook | SOUTH | Gate at the back of the allotment is in poor condition (fencing which can be jumped over even though there is barbed wire on the top). The allotment is prone to flooding due to the channel and the brook that goes through the allotment. Fencing needs installing along canal side | 101 | 0 | 8 | 352 | £24,640 |
| Lord Street | SOUTH | Pathway leading up to gate between houses 118 & 120, the gates needs to be adjacent to the pavement. The gate is secure with 2 locks. The gate itself is crisscross wired, and have barbed wire on top of the gate, would be desirable to change this gate. The fencing has just been recently done. There are 2 plots which have been fenced off due to the trees with a gate to access it. Fencing border is very good. The fencing by Patriot Close (southern border) needs to be done | 75 | 0 | 4 | 116 | £8,120 |
| Queens Lea | WEST | All of the fencing needs to be done around the perimeter. | 12 | 0 | 10 | 261 | £18,270 |
| Slaters Lane | SOUTH | Pallasade front gate in good condition. The front fencing is 7 ft green hardcore mesh in very good condition. The right side overlooks the railway which has trees, hedges and bushes which is mixed in with a few metres of pallasade in places - right side may require fencing as they do occasionally get people jumping over from the railway. Back of allotments again bushes, brambles, trees which is very thick, desirable to have fencing at back, but not essential. | 60 | 4 | 0 | 393 | £27,510 |
| Trees Road | SOUTH | Fencing required from Delves Road all around the border. Gate is fine, but need fencing around the gate as coming off the hinges and made of wood which is crumbling | 13 | 3 | 0 | 340 | £23,800 |

| | | | | | | | |
|----------------|-------|---|-------------|-----------|------------|-------------|-----------------|
| Victoria Road | WEST | Left side has half pallasade from the main road towards the middle, then it turns private fencing which is half wooden. Left side of allotment needs to be improved. Back of allotment needs fencing, as conifers are pushing back the posts. | 54 | 0 | 10 | 155 | £10,850 |
| Winterley Lane | EAST | Wooden fence at rear of car park is privately owned - in need of improvement / Perimeter of the allotment is pallasade metal fencing (Good) / Metal gates double locking (Good) | 41 | 0 | 11 | 26 | £1,820 |
| Wrexham Avenue | SOUTH | Security issues from front gate, prone to ASB and the plot holders are very wary of them trespassing onto the allotment. The fencing needs to be replaced on the right hand side which is broken and not secure. | 39 | 2 | 5 | 350 | £24,500 |
| | | | 1352 | 29 | 252 | 3713 | £259,910 |