


Walsall Council's Gulley Cleaning Programme


John Roseblade

Group Manager Engineering and Transportation









│ E Kaarbon Tech Surveying ※ │		pur ille
← → C 🗋 walsall.kaarl	oontech.co.uk/office/index.html#workSpace/W/asset/40001943	ů
	Gully #40001943 'WSAB4248'	× Close
	e Gully (< 1.2m deep, invert level 60cm, Cast iron cover) NE Parish/Ward: Aldridge Central And South; Direct access OK	
> Previous records (1)		
 Most recent inspect 	ion #40033056 completed 2 April 2014 13:54	
Any comments:		
Inspection complete	2 April 2014 13:54	
> Inspection type: Cycli	cal	
> Accessible; No traffic	management required	
> Cleaned; Not Jetted; C	over OK; Silt 75% (tarmac/stone); Operational on leaving; Operational on arrival	
> Photo (none)		
Any comments:		
Inspection complete	2 April 2014 13:54	

